



# Automated Inspection- & Service Reports

Convert paper-based inspection- or service procedures into step-by-step digital work processes, with on-demand live access to MyRoom, documentation and other vital resources such as ITP's, DVTs, FATs, Testing- and Service Reports. Reports are generated and distributed instantly when a job has been completed, using a standard or customized template to ensure compliance with end user requirements. Additionally, the system is able to interface with any ERP system, Excel or other applications supported by Zapier®. It can create actions including email notifications when a report is completed or when triggered by a specific workflow step. Providing full access to the admin dashboard enabling key users to manage workflows, set pre-planned work schedules, set actions/triggers, run reports and set user access preferences. If you are interested to utilize the benefits of Automated Inspection- or Service Reporting, Vmatch can provide a proof-of-concept to automate a 'simple' workflow showing the benefits and savings this solution can bring to your organization. Tailor-made solutions at your request!

This use of proof-of-concept helps to establish viability and scalability of;

- ✓ Automation of work procedures / on-site inspection- & service reporting
- ✓ MyRoom workstream integration
- ✓ Pre-installed App's and ready to use on each HMT-1, smartphone or tablet
- ✓ Safe & secure data storage, on premises or cloud hosting
- ✓ ERP/IT systems interfaces
- ✓ Training-, support- and user license needs
- ✓ Further (field) service applications, benefits and cost savings





GOODS INSPECTION REPORT				
Supplier Name : Virtual Valves Ltd		Supplier Code : part no. 203456890660		
Supplier Address : London England W1T 1JY		Goods Information : High Pressure Globe Valve 4"		
PO No : VVL_2020_006234		PO Date : 17/07/2020		
		Goods Received Date : 18/08/2020		
No	Description	Test Result	Status	
			Accepted	Rejected
001	Visual Inspection according to APGD (AP058)	sand casting defects on the surface		X
	Part no. 203456890660			
	Vendor PO: 20203458_item 1			
Evidence Links		Zapier® trigger/workflow step Action by: PV_19.08.202_NCR_Email notification Confirmed: yes		
Total Received Quantity	Total Acceptable Quantity	Total Rejected Quantity	Total Returned Quantity	Total In Process Quantity
1	0	1	1	1
Inspector Name/Signature/Date		Start : 19/08/2020 : 11:17am		
Andrew G. Ticket		Finish : 19/08/2020 : 11:45am		
ISO 9712 NDI level III		GPS/GSD Tag: 43°24'12.2"N 2°10'26.5"E		
Global Veritas Ltd		EnergyWeb record: #3f24ba5f6a30e1e1832ac30ac29e310305c51a7942e710		



[www.vmatch.nl](http://www.vmatch.nl)

[info@vmatch.nl](mailto:info@vmatch.nl)





## STEP-BY-STEP DIGITAL WORK PROCESSES

Verification of on-site worker

Select a pre-defined workflow

Activate a job

Follow pre-defined workflow and steps

Verification of product/asset;  
Barcode, QR code, speech to text interaction

Easy access to specifications, documents, P&ID's, files, manuals and remote experts on demand


Verify & validate data with industry standards and/or customer specifications

Data acquisition / NDT instruments (IIoT's)


[www.vmatch.nl](http://www.vmatch.nl)

[info@vmatch.nl](mailto:info@vmatch.nl)







Clear instructions via text, text to speech engine or earphones



Hands-free, built in speech to text interaction, noise controlled



Evidence collection; photos, videos, comments



Deliver the data you need to effectively report back and manage compliance














Sign off

[www.vmatch.nl](http://www.vmatch.nl)

[info@vmatch.nl](mailto:info@vmatch.nl)



On-site report generator, audit evidence/verification trail  
with indisputable footage and punch-list

GOODS INSPECTION REPORT																																																																																																										
Supplier Name : Virtual Valves Ltd		Supplier Code : part no. 203456890660																																																																																																								
Supplier Address : London England W1T 1JY		Goods Information : High Pressure Globe Valve 4"																																																																																																								
PO No VVL_2020_006234	PO Date 17/07/2020	Goods Received Date 18/08/2020																																																																																																								
<table border="1"> <thead> <tr> <th rowspan="2">No</th> <th rowspan="2">Description</th> <th rowspan="2">Test Result</th> <th colspan="2">Status</th> </tr> <tr> <th>Accepted</th> <th>Rejected</th> </tr> </thead> <tbody> <tr> <td></td> <td>Visual Inspection according to API6D (API598)</td> <td></td> <td></td> <td></td> </tr> <tr> <td>001</td> <td>High Pressure Globe Valve 4"</td> <td>sand casting defects on the surface</td> <td></td> <td>X</td> </tr> <tr> <td></td> <td>Part no. 203456890660</td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>Vendor PO: 20203458_item 1</td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="5"> <table border="1"> <thead> <tr> <th>Total Received Quantity</th> <th>Total Acceptable Quantity</th> <th>Total Rejected Quantity</th> <th>Total Returned Quantity</th> <th>Total In Process Quantity</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>0</td> <td>1</td> <td>1</td> <td>1</td> </tr> </tbody> </table> </td> </tr> <tr> <td colspan="5"> <p>Evidence Links   </p> <p>Zapier® trigger/workflow step Action by: PV_19.08.202_NCR_Email notification Confirmed: yes</p> </td> </tr> <tr> <td colspan="5">Inspector Name/Signature/Date</td> </tr> <tr> <td colspan="2">Andrew G. Ticket ISO 9712 NDT level III Global Veritas Ltd</td> <td colspan="2">                       EnergyWeb record: #2cf24dba5fb0a30e26e83b2ac5b9e29e1b161e5c1fa7425e730                 </td> <td>                     Start 19/08/2020_11.17am                      Finish 19/08/2020_11.45am                      GPS/GEO Tag: 41°24'12.2"N 2°10'26.5"E                 </td> </tr> </tbody> </table>					No	Description	Test Result	Status		Accepted	Rejected		Visual Inspection according to API6D (API598)				001	High Pressure Globe Valve 4"	sand casting defects on the surface		X		Part no. 203456890660					Vendor PO: 20203458_item 1																																																	<table border="1"> <thead> <tr> <th>Total Received Quantity</th> <th>Total Acceptable Quantity</th> <th>Total Rejected Quantity</th> <th>Total Returned Quantity</th> <th>Total In Process Quantity</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>0</td> <td>1</td> <td>1</td> <td>1</td> </tr> </tbody> </table>					Total Received Quantity	Total Acceptable Quantity	Total Rejected Quantity	Total Returned Quantity	Total In Process Quantity	1	0	1	1	1	<p>Evidence Links   </p> <p>Zapier® trigger/workflow step Action by: PV_19.08.202_NCR_Email notification Confirmed: yes</p>					Inspector Name/Signature/Date					Andrew G. Ticket ISO 9712 NDT level III Global Veritas Ltd		 EnergyWeb record: #2cf24dba5fb0a30e26e83b2ac5b9e29e1b161e5c1fa7425e730		Start 19/08/2020_11.17am Finish 19/08/2020_11.45am GPS/GEO Tag: 41°24'12.2"N 2°10'26.5"E
No	Description	Test Result	Status																																																																																																							
			Accepted	Rejected																																																																																																						
	Visual Inspection according to API6D (API598)																																																																																																									
001	High Pressure Globe Valve 4"	sand casting defects on the surface		X																																																																																																						
	Part no. 203456890660																																																																																																									
	Vendor PO: 20203458_item 1																																																																																																									
<table border="1"> <thead> <tr> <th>Total Received Quantity</th> <th>Total Acceptable Quantity</th> <th>Total Rejected Quantity</th> <th>Total Returned Quantity</th> <th>Total In Process Quantity</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>0</td> <td>1</td> <td>1</td> <td>1</td> </tr> </tbody> </table>					Total Received Quantity	Total Acceptable Quantity	Total Rejected Quantity	Total Returned Quantity	Total In Process Quantity	1	0	1	1	1																																																																																												
Total Received Quantity	Total Acceptable Quantity	Total Rejected Quantity	Total Returned Quantity	Total In Process Quantity																																																																																																						
1	0	1	1	1																																																																																																						
<p>Evidence Links   </p> <p>Zapier® trigger/workflow step Action by: PV_19.08.202_NCR_Email notification Confirmed: yes</p>																																																																																																										
Inspector Name/Signature/Date																																																																																																										
Andrew G. Ticket ISO 9712 NDT level III Global Veritas Ltd		 EnergyWeb record: #2cf24dba5fb0a30e26e83b2ac5b9e29e1b161e5c1fa7425e730		Start 19/08/2020_11.17am Finish 19/08/2020_11.45am GPS/GEO Tag: 41°24'12.2"N 2°10'26.5"E																																																																																																						

